







1BR - TYPE A1




1BR - TYPE A2




3RD FLOOR




6TH FLOOR




9TH FLOOR




12TH FLOOR




14TH FLOOR




10TH FLOOR




11TH FLOOR




14TH FLOOR




2ND FLOOR




5TH FLOOR




8TH FLOOR




11TH FLOOR




13TH FLOOR



4TH FLOOR



7TH FLOOR




10TH FLOOR


DAMAC PROPERTIES L.L.C.

DAMAC HILLS 2


X-MU-B2




1BR - TYPE A3




3RD FLOOR




6TH FLOOR




9TH FLOOR




12TH FLOOR




14TH FLOOR




2ND FLOOR




5TH FLOOR




8TH FLOOR




11TH FLOOR




13TH FLOOR




1ST FLOOR



4TH FLOOR



7TH FLOOR




10TH FLOOR


DAMAC PROPERTIES L.L.C.

DAMAC HILLS 2


X-MU-B2




1BR - TYPE B1




1BR - TYPE B2




3RD FLOOR




6TH FLOOR




9TH FLOOR




12TH FLOOR




14TH FLOOR




1ST FLOOR




2ND FLOOR




5TH FLOOR




8TH FLOOR




11TH FLOOR




13TH FLOOR




1ST FLOOR



4TH FLOOR



7TH FLOOR




10TH FLOOR


DAMAC PROPERTIES L.L.C.

DAMAC HILLS 2


X-MU-B2




2BR - TYPE A1




2BR - TYPE A2




3RD FLOOR




6TH FLOOR




9TH FLOOR




12TH FLOOR




14TH FLOOR




5TH FLOOR




11TH FLOOR




14TH FLOOR




2ND FLOOR




5TH FLOOR




8TH FLOOR




11TH FLOOR




13TH FLOOR




4TH FLOOR




10TH FLOOR




1ST FLOOR




4TH FLOOR




7TH FLOOR



10TH FLOOR



3RD FLOOR




7TH FLOOR


DAMAC PROPERTIES L.L.C.

DAMAC HILLS 2



X-MU-B2




2BR - TYPE A3




2BR - TYPE A4






2BR - TYPE B1




1ST FLOOR




2BR - TYPE B2


- LEVEL 14
- LEVEL 13
- LEVEL 12
- LEVEL 11
- LEVEL 10
- LEVEL 9
- LEVEL 8
- LEVEL 7
- LEVEL 6
- LEVEL 5
- LEVEL 4
- LEVEL 3
- LEVEL 2




3RD FLOOR




6TH FLOOR




9TH FLOOR




12TH FLOOR




14TH FLOOR




2ND FLOOR




5TH FLOOR




8TH FLOOR




11TH FLOOR




13TH FLOOR



4TH FLOOR



7TH FLOOR




10TH FLOOR


DAMAC PROPERTIES L.L.C.

DAMAC HILLS 2

X-MU-B2



2BR - TYPE B3



DAMAC PROPERTIES L.L.C.

DAMAC HILLS 2

X-MU-B2